

MGSP Quarterly Visual Assessment Form

Name of Facility:	Fairbanks International Airport
APDES Tracking #:	AK R06AB76
Date of Sample Collection and Visual Assessment:	9/21/18
Weather Conditions/Notes:	Cloudy/Rainy 50°
Snowmelt Runoff or Rainfall Event?	Rainfall
Rainfall: Duration, Inches, and Time Since Prior Rain	Unknown, ~ 0.5 in, 0 days
If sample collection process not started within 30 minutes of rainfall give reason:	Not practicable

Site #	Outfall Site Name	Discharge at Site?	Sample Taken in Clean, Clear Container?	Sample Inspected in Well Lit Area?	Time of Assessment	Any of the following present? Color, odor, clarity, floating solids, settled solids, suspended solids, foam, oil sheen, strains at outfall? <u>If yes, describe.</u>
3	SW Terminal Pond	N/A	N/A	N/A	9:05	N/A
The bottom half of the culvert was full of water as it was level with the pond. Sample was not collected access to reach in culvert to collect sample in culvert was implacable. No stains, foam, or sheen were visible in the water closest to the culverts outfall.						
4	NW Terminal Pond	N/A	N/A	N/A	9:10	N/A
Access to this culvert was impaired by small trees and shrubs. Collection of this sample would have been unsafe, therefore sampling this outfall was impracticable. No stains, foam, or sheen were visible in the water closest to the culverts outfall.						
5	Remnant Slough	Yes	Yes	Yes	9:20	None
7	Float Pond	Yes	Yes	Yes	9:25	None
9	E Wetlands	No	N/A	N/A	13:30	N/A
10	NE Wetlands	No	N/A	N/A	13:35	N/A

Inspector Name: Ashley Jaramillo Title: Environmental Manager Signature: 